

Parts needed for Coach-Diner GN 1146



Coach Seat Arm Inside Finish

Bill of Materials p106

Need two left-side arm inside finish pieces for Heywood Wakefield 820-P-41-ET sleepy hollow rotating seat. (44 inch long overall.)