

Parts needed for Coach-Diner GN 1146



## Coach Seat Arm Rest

Bill of Materials p106

Need three arm rests for Heywood Wakefield 820-P-41-ET sleepy hollow rotating seat. (44 inch long overall.)

Ruler shows approx 6 1/4" between mounting holes.