



Parts needed for Coach-Diner GN 1146



End door handle races

Bill of Materials p183

Dayton Manufacturing Co's drawing #49K/D1019A for 1 1/4" thick door

Need four end door handle races. (The portion which captures the handle to limit its travel.)