

Parts needed for Coach-Diner GN 1146



## Tail Gates

Bill of Materials p112

Need two ACF tail gates. (Existing are damaged.)

Tape measure shows 40  $\frac{3}{4}$  inch height.